




Year 10 Engineering



Projection	Symbol
First angle	
Third angle	

Outlines	
Construction lines	
Hidden details	
Dimension arrow	
Centre line	



Working drawings

Working drawings are sent from a designer to a **manufacturer** to enable them to build a product.

Exploded diagrams show how a product can be assembled and how the separate parts fit together, with dotted lines showing where the parts slide into place. The diagrams also show components that would usually be hidden in a solid drawing.